

# POPCORN

## Included Items:

Popcorn Machine  
Plastic Scoop  
Pre-measured Popcorn and Oil  
Popcorn Boxes  
Extension Cord



## Operating Instructions

- Place the machine on a sturdy table or countertop
- Open door and lower drop panel
- Turn on Kettle Heat Switch, Motor Switch, and Light/Warmer Switch
- Flip Open Kettle Lid
- Open pre-measured oil and popcorn kit
- Empty into Kettle (will heat up in 3-4 min)
- When popcorn is almost done dump kettle twice

***Do not wait for all popping to stop; popcorn will burn. Some un-popped kernels are normal.***

- Repeat process until desired amount of popcorn is popped
- Turn off Kettle Heat Switch and Motor Switch after completing final batch
- Keep Light/Warmer turned on until finished serving.



### WARNING

**Do Not let minor operate machine  
Do Not touch Kettle when popping  
(IT'S HOT)**